



# EAGLE MOUNTAIN HS



Aerial of the north side of the property





**Aerial of the west side of the property**





Aerial of fine arts and gymnastics





Main academic area steel is in progress.





Paving on the west entrance that connects to the south entrance is in progress.







Work continues on the home side of the stadium. Grade beam structure is ready for pour.





**View from field level towards  
the visitor sideline**



**View of the auxiliary field final grade**





# ELIZABETH LOPEZ HATLEY ES



Aerial of property looking south





Work on the ICF in the cafeteria continues. Grease trap has been installed.







Piers and storm water continue to progress.





# WAYSIDE MS



**Now that middle school football season is over, track repairs have begun. The track will be complete for track season.**